


Exploded

H3005 Lateral Raise



please note :parts didn't demolitionde part and fasteners not listde on the introduction

D4	Foam Frame	PI002	1
D3	Pin	φ8*50	8
D2	Socket Cap inner hex	M10*16	2
C19	Outer hex screw	M12*80	4
C15	Self lock nut	M12	4
C2	Flat washer	φ 10	8
C1	Cup head inner hex screw	M8*35	8
A21	Spring washer	φ 12	22
A19	Outer hex screw	M12*35	14
A16	Gasket	D0003	22
A15	Screw cap	S208	22
A6	Cup head inner hex screw	M5*15	8
A5	Cup head cross tapping screw	S13*8	4
A3	Top cover		1
A2	Back shroud		1
A1	Front shroud		1
12	Bearing fixing		1
10	Cam frame		2
09	Handle frame		2
08	Working arm		2
07	Pulley set frame		1
06	Seat fixing frame		1
05	Custom selection		1
04	Main frame		1
03	Bottom connector		1
02	Bent frame set		1
01	Door frame		1
序号	名称		数量